

9-23-15

FormEditor.txt

Follow up site visit to verify empty pool and to see if construction had started. Results-Not impounding water and construction had started. Large area where sinkhole was to the building was removed. This exposed the outlet pipe and revealed it was weakened by rust and penetrated by the earth mover during excavation.

21-23-9



































