



**Preliminary Inspection Report for South Carolina
Regulated Dams and Impoundment Structures
Regulations
R.72-1 through R.72-9**

Section I (Owner's Information)

A. Dam Number: D 0026 & Hazard Class C1 B. Name of Dam: Cary's Lake Dam
C. Inspection Date (12/30/2013) & Time: _____ D. Date of Last Inspection: (12/10/2012)
E. Location-County/City: _____ / _____ F. EQC Regional Office: Region 3-Columbia
G. Inspector's Name: Steven Hauptmann
H. Owner's Name: CARY'S LAKE HOA, INC
I. Contact Person (if different from above): STEVE BROWN
J. Dam Owner's or Contact Person's Phone Numbers: Home (803) 785 - 3515
Office (____) ____ - ____
Other (____) ____ - ____
K. Dam Owner's or Contact Person's mailing address:
Address 1 6748 CARY LANE
Address 2 (optional) _____
City COLUMBIA, State SC Zip Code 29206 - ____

Section II (Dam Condition)

General Condition Assessment (Select one of the following):

a) Satisfactory ☒ b) Fair ☐ c) Poor ☐ d) Unsatisfactory ☐ e) Not Rated ☐

Section III (Dam Inspection Checklist)

A. Dam Crest

i. Vegetation (grass, trees weeds)? ROADWAY-ARCADIA LAKES DR E
ii. Animal activity observed? NO
iii. Any obvious alteration or repairs made? NO
iv. Erosion noticed on crest? NO
v. Any visible settlement, misalignment or cracks? NO

Section III (Dam Inspection Checklist) continued

B. Upstream Slope

i. Vegetation (grass, trees weeds)? GOOD GRASS COVER

ii. Animal activity observed? NO

iii. Any obvious alterations or repairs made? NO

iv. Erosion observed on upstream slope? INSIGNIFICANT

v. Settlement or cracks visible in slope? NO

C. Down Stream Slope

i. Vegetation (grass, trees weeds)? GOOD GRASS COVER

ii. Animal activity observed? NO

iii. Any obvious alterations or repairs made? NO

iv. Erosion observed on down stream slope? SLIGHT SLIDING IN SMALL AREA BUT HAS GRASS COVER-WILL MONITOR

v. Settlement or cracks visible in slope? NO

vi. Toe drains flowing?

vii. Any seepage observed? If so, describe location, flow rate, and any turbidity or color within the flow: NO

D. Primary Spillway

i. Any visible deterioration of structure? NO

ii. Is there an obvious need to repair or replace trash rack? NO

iii. Any noticeable problems with debris? NONE

iv. Is valve or gate present? YES

E. Outlet Pipe

i. Any water visibly flowing or leaking outside of the discharge pipe? NO

ii. Describe any deflection or damage observed to the pipe: NONE

iii. Visible condition of outlet channel: GOOD

F. Auxiliary (Emergency) Spillway

i. Noticeable obstructions to flow? NO

ii. Animal activity observed? NONE

iii. Any noticeable deterioration in the approach or discharge channel? NONE

iv. Any visible deterioration of structure's crest? NO

F. Auxiliary (Emergency) Spillway continued

v. If applicable, any observed exposure of rebar reinforcement? NO

vi. If applicable, any visible leakage below concrete spillway? NO

H. Downstream/Hazard Class Issues

i. Any noticeable changes immediately downstream of the dam that affects the hazard classification? NO

I. Emergency Action Plan (EAP)

i. Emergency Action Plan provided by owner? YES, BUT NEED UPDATED PLAN-WILL SEND WITH REPORT

ii. Does EAP contains emergency alert notification plan? If so, when was it last updated? 2008

iii. Does EAP contain specific actions to take if the dam has failed or is near failure? _____

Section IV (Conclusions)

General comments and recommendations:

Dam remains in good condition and no significant problems are visible or expected.

Possible upgrade would be to add additional rip-rap to prevent wave induced erosion (boats, personal watercraft).

Preliminary Dam Inspection Disclaimer:

The information contained in the preliminary inspection report is intended as an aid to identify those dams that require maintenance and/or repair actions to reduce their danger to human life or property only. It is not intended as professional engineering or consulting advice for conditions or situations present at individual dams. It is not a substitute for a detailed inspection, nor does it replace the need for services provided by registered professional engineers. If your dam is experiencing an unusual situation consult with engineering professionals to find an appropriate remedy. Preliminary inspections conducted by South Carolina Department of Health and Environmental Control (the Department) are provided "AS IS" and "as available", without warranties of any kind, either express or implied. Preliminary inspections consist only of a visual but technical examination of the dam and its appurtenant works. All findings are based solely on visual observations of the inspector at the time of the inspection. Common law holds that the storage of water is a hazardous activity and the Department does not assume any responsibility or risk for your actions or inactions. Dam owners are responsible for the safe operations and maintenance of their impoundment structures.