



CENTRAL MIDLANDS EQC DISTRICT
PO Box 156, Building #5
State Park, SC 29147

June 5, 1998

Stephen F. Morris
Lake Dogwood LLC
320 Country Club Dr.
Columbia, SC 29209

RE: Reinspection of Dam D-0595, Murray Pond Dam (Lake Dogwood Dam), Richland County

Dear Mr. Morris:

On Thursday, June 4, 1998, I conducted a routine reinspection of the above referenced dam. I would like to thank you and T. Moffat Burris for meeting with me for the inspection.

I am enclosing a copy of the inspection report on the dam. Overall, the dam appears to be in good condition. (NOTE: Any deficiencies are listed on the inspection report)

I have verified the telephone numbers on the Emergency Notification Plan and a copy is enclosed for your use. Should the dam experience difficulty, you should contact all of the numbers on the plan. The agencies listed on the plan can provide assistance in blocking roads and doing other things that need to be done in the event of an emergency.

Provisions in the SC Dams and Reservoirs Safety Act require the owner to notify us (SC DHEC) within thirty (30) days after transferring title or control of a dam to someone else. The notification must include the name, address and telephone number of the new owner. I am enclosing a blank form for your use in notifying us should control of your dam be transferred.

You will be notified when the next reinspection of this dam is scheduled.

Sincerely,

Kendrick R. Chiles
Environmental Engineer Associate
Central Midlands EQC District Office

Enclosures

cc: Richard Yongue, DHEC Bureau of Water Facilities Compliance

INSPECTION REPORT

Date June 4, 1998

Dam Murray Pond Dam, D-0595

Representatives of SCDHEC Present: Kendrick R. Chiles

Representatives of Owner Present: Stephen F. Morris

Others Present: T. Moffat Burriss

List of noted deficiencies or items requiring correction/checking:

*Vegetation and trees should be removed from middle of dam/spillway.


*Area to right of dam should be cleared of vegetation, trees (less than 6" in diameter),
and all dead trees and limbs immediately. When trees are removed the stumps should
also be removed and the area filled in with clay material. This area should be
monitored closely for future erosion or other problems.

NOTE: Dam should remain clear of vegetation year round.

List of previously noted items still uncorrected and dates previously noted:

None

Emergency Action Plan Updated Yes x No



Signature of Person Completing Form

**NOTIFICATION OF OWNERSHIP CHANGE
S.C. REGULATED DAM**

Date

The ownership of Dam D _____, _____ in
(Name of Dam)

_____ County has changed. The new owner(s) are:

Owner 1* _____

Address _____

City, State, Zip _____

Telephone Number _____

Owner 2* _____

(if applicable)

Address _____

City, State, Zip _____

Telephone Number _____

Additional Owner* _____

(if applicable)

Address _____

City, State, Zip _____

Telephone Number _____

*If owner is a corporation, give name of principal contact person:

(Previous Owner's Signature)

Previous Owner's Name

Previous Owners Address

Mail Above Notification To:

S.C. Department of Health and Environmental Control
Dams and Reservoirs Safety
2600 Bull Street
Columbia, SC 29201

NOTE: Failure to notify the S.C. Department of Health and Environmental Control within 30 days of ownership transfer can result in a fine of \$100 - \$1000.

DHEC 2605(6/94)