# **SCANNED**





SEP 1 6 2019

SCDHEC, BLWM Kim Kuhn 2600 Bull Street Columbia, SC 29201

GITE ASSESSMENT, REMEDIATION & REVITALIZATION Westinghouse Electric Company Nuclear Fuel Columbia Fuel Fabrication Facility 5801 Bluff Road Hopkins, South Carolina 29061 USA

Direct tel: 803.647.1920 Direct fax: 803.695.3964

e-mail: joynerdp@westinghouse.com

Your ref:

Our ref: LTR-RAC-19-73

September 12, 2019

Subject: RI Work Plan Additional Floodplain Assessment
Results and Permanent Well Installation Recommendations

Mrs. Kuhn:

Please find attached for your consideration the results of the additional floodplain assessment and the proposed locations for the four permanent floodplain wells.

Respectfully,

Diana P. Joyner

Principal Environmental Engineer

Westinghouse Electric Company, CFFF

803.497.7062 (m)

cc:

E. Wills, EH&S Manager

N. Parr, Environmental Manager
J. Grant, AECOM Project Manager

**ENOVIA Records** 

Enc.:

"Columbia Fuel Fabrication Facility, Floodplain Assessment Results, RI Work Plan, AECOM, File

#51377.

A=COM

**AECOM** 101 Research Drive Columbia, SC 29203 (803)254-4400 (803)771-6676



SEP 1 6 2019

TE ASSESSMENT. EMEDIATION &

SVITALIZATION

September 12, 2019

Ms. Kimberly M. Kuhn, Project Manager State Voluntary Cleanup Section Division of Site Assessment, Remediation and Revitalization Bureau of Land and Waste Management 2600 Bull Street Columbia, S.C. 29201

Subject:

Columbia Fuel Fabrication Facility Floodplain Assessment Results

Richland County, S.C.

Consent Agreement CA-19-02-HW

File # 51377

Dear Ms. Kuhn:

Based upon our September 9, 2019 meeting, AECOM submits the following additional floodplain assessment analytical results and proposed floodplain well installation information.

### Background

On August 2, 2019, AECOM submitted a plan on behalf of the Westinghouse Columbia Fuel Fabrication Facility (CFFF) to conduct vertical groundwater profiling in the Congaree River floodplain. This additional floodplain assessment was approved on August 7. The profiling targeted conductive sand units within the floodplain to obtain groundwater samples from temporary wells on the southern side of Upper Sunset Lake and northeast of Lower Sunset Lake. Groundwater samples were collected from multiple intervals in each borehole location. Prior to sample collection, stabilization parameters were monitored to ensure groundwater being pumped from the temporary well was indicative of groundwater quality at each discrete groundwater sampling interval.

#### **Groundwater Analytical Results**

Groundwater south of Upper Sunset Lake was analyzed for chlorinated volatile organic compounds (CVOCs) because CVOCs are the only known constituent of potential concern (COPC) that would migrate within the groundwater in this area based upon previous groundwater assessment activities. Using the same reasoning, groundwater northeast of Lower Sunset Lake was analyzed for CVOCs, fluoride and nitrate.

Table 1 contains a summary of the sample locations, generalized geology at each sample location, groundwater sampling intervals, detected COPCs and proposed floodplain well designation and associated screened interval.

To enhance and sustain the world's built, natural and social environments

## **Proposed Permanent Well Locations**

Per the April 2019 Remedial Investigation Work Plan, four floodplain wells (W-94 through W-97) will be installed during this phase of work. The locations of these wells are based upon data collected from this additional floodplain assessment. Proposed floodplain well locations are displayed on the attached **Figure 1**. Proposed screened intervals are contained in the attached **Table 1**.

Should you have any questions regarding the information provided in this plan, please do not hesitate to contact AECOM at (803) 254-4400.

Kiemy Straw

Sincerely,

Chuck Suddeth, P.G. Project Geologist

Charles K Suboth

Jeremy Grant, P.G. Project Manager

Attachments: Table 1 – Vertical Groundwater Profiling Results

Figure 1 – Proposed Floodplain Well Locations

Cc: Nancy Parr, CFFF Diana Joyner, CFFF Ed Wills, Jr., CFFF

#### Table 1 Westinghouse Columbia Fuel Fabrication Facility Additional Floodplain Assessment Vertical Groundwater Profiling Results

Samp <b>le Locat</b> ion	Depth Interval (feet)	Generalized Lithology	Sampling Interval(s) (feet)	Detected Analytes	Proposed Well/Screened Interval
L-1 -	0-8.5	Clayey silt	-	-	
	8.5-33.5	Sand	10-15	ND	
			28-33	Cis-1,2-DCE = 3.8 ug/L., VC = 2.7 ug/L	W-95, 28-33
	33,5-45	Silt	-	-	
	45-83	Sand	48-53	ND	
			63-68	ND	
			78-83	ND	
	83-86	Clay	-	-	
L-8	0-8	Clayey silt	-	-	
	8-22	Sand -	8-13	F = 0.26 mg/L, NO <sub>3</sub> = 0.081 mg/L	
			17-22	ND	
	22-25	Silty clay	-	-	
	25-46	Sand -	25-30	PCE = 2.2 ug/L, TCE = 2.1 ug/L	W-96, 25-30
			41-46	F = 0.14 mg/L	
	46-47	Clay	2	-	
L-9	0-10	Clayey silt	-	-	
	10-28.5	Sand .	10-15	PCE = 6.5 ug/L, TCE = 3.0 ug/L, F = 0.48 mg/L, $NO_3 = 5.4$ mg/L	W-97, 13-18
			23-28	ND	
	28.5-32	Silty clay		-	
	32-34.5	Sand and gravel	32-37	ND	
	34.5-37.5	Clayey sand	-	-	
	37.5-43.5	Clay	-	-	
L-10	0-9	Clayey silt	-	-	
	9-22,5	Sand	9-14	NO <sub>3</sub> = 1.1 mg/L	
			18-23	NO <sub>3</sub> = 0.18 mg/L	
	22.5-24.5	Silty clay	-	-	
	24.5-33.5	Sand	28-33	NO <sub>3</sub> = 0.19 mg/L	
	33.5-38.5	Clay	-	-	
L-17	0-11	Silt	-		
	11-20.5	Sand	15-20	Cis-1,2-DCE = 6.2 ug/L	
	20.5-27	Silty Sand		-	
	27-29	Sand	25-30	Cis-1,2-DCE = 5.4 ug/L	W-94, 24-29
	29-47	Clay	-	-	

# Table 1 Westinghouse Columbia Fuel Fabrication Facility Additional Floodplain Assessment Vertical Groundwater Profiling Results

Sample Location	Depth Interval (feet)	Generalized Lithology	Sampling Interval(s) (feet)	Detected Analytes	Proposed Well/Screened Interval
L-18	0-14	Silt	-	2-	
	14-32	Sand	15-20	NÐ	
			24-29	Cis-1,2-DCE = 1.2 ug/L, VC = 1.1 ug/L	
	32-37	Clay	-	-	
L-19	0-8	Clayey Silt	-	-	
	8-12	Silty Sand	7-12	F = 7.8 mg/L, NO <sub>3</sub> = 0.092 mg/L, Cis-1,2-DCE = 1.0 ug/L, Trans-1,2-DCE = 1.3 ug/L.	
	12-21	Clay	•	-	
	21-26	Sand	21-26	F = 0.16 mg/L, NO <sub>3</sub> = 0.10 mg/L	
	26-29	Clay	н	-	

#### Notes:

CVOCs - chlorinated volatile organic compounds
EPA - United States Environmental Protection Agency
ND - None detected

